

WEST Search History

DATE: Thursday, July 26, 2007

Hide?	<u>Set</u> <u>Name</u>	<u>Query</u>	<u>Hit</u> <u>Count</u>
	<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L31	l8 and (retained near austenit\$2 near grain)	21
<input type="checkbox"/>	L30	L29 and (austenit\$2 adj grain)	225
<input type="checkbox"/>	L29	l8 and forg\$3 and (cool\$3 or quench\$3)	804
<input type="checkbox"/>	L28	l8 and 148/660-663.ccls.	129
<input type="checkbox"/>	L27	l8 and 148/654.ccls.	185
<input type="checkbox"/>	L26	l8 and 148/648.ccls.	33
<input type="checkbox"/>	L25	l8 and 148/646.ccls.	0
<input type="checkbox"/>	L24	L23 and (ferrit\$2 same austenit\$2 same (bainit\$2 or martensit\$2))	172
<input type="checkbox"/>	L23	l8 and 148/333-336.ccls.	291
<input type="checkbox"/>	L22	l8 and 420/104-112.ccls.	144
<input type="checkbox"/>	L21	l8 and 420/8.ccls.	14
<input type="checkbox"/>	L20	l8 and 420/\$.ccls.	745
<input type="checkbox"/>	L19	L18 and grain	150
<input type="checkbox"/>	L18	L17 and (ferrit\$2 same austenit\$2 same (martensit\$2 or bainit\$2))	179
<input type="checkbox"/>	L17	l8 and 148/320.ccls.	267
<input type="checkbox"/>	L16	L13 and (ferrit\$2 near austenit\$2 near (martensit\$2 or bainit\$2))	36
<input type="checkbox"/>	L15	L13 and 148/\$.ccls.	535
<input type="checkbox"/>	L14	L13 and grain	622
<input type="checkbox"/>	L13	l8 and forg\$3	855
	<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L12	l6 same grain	143
	<i>DB=PGPB,USPT,USOC,EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L11	steel same (c or carbon) same (si or silicon or al or aluminum) same (mn or manganese) same (ferrit\$2 near austenit\$2 near (martensit\$2 or bainit\$2))	32
<input type="checkbox"/>	L10	l8 and (Ae1 or Ae3)	20
<input type="checkbox"/>	L9	L8 and 148/649.ccls.	24
<input type="checkbox"/>	L8	steel and (c or carbon) and (si or silicon or al or aluminum) and (mn or manganese) and (martensit\$2 or bainit\$2) and (ferrit\$2) and (austenit\$2)	3361
	<i>DB=EPAB,JPAB,DWPI; PLUR=YES; OP=OR</i>		
<input type="checkbox"/>	L7	L6 same forg\$2	5
	L6	steel same (c or carbon) same (si or silicon or al or aluminum) same (mn or	638

<input type="checkbox"/>		manganese) same ferrit\$2 same austenit\$2 same (martensit\$2 or bainit\$2)	
<input type="checkbox"/>	L5	L4 same (martensit\$2 or bainit\$2)	12
<input type="checkbox"/>	L4	L3 same ferrit\$2 same austenit\$2	39
<input type="checkbox"/>	L3	l1 same (c or carbon) same (si or silicon or al or aluminum) same (mn or manganese)	1803
<input type="checkbox"/>	L2	L1 same Ae1	2
<input type="checkbox"/>	L1	steel same forg\$3	6871

END OF SEARCH HISTORY